

RECEIVED

SEP 16 1982

**MINERALS MANAGEMENT SERVICE
ALBUQUERQUE, NEW MEXICO**

ROUTE

ROUTE

<i>dcj</i>	Dist. Svc.	<i>9/16</i>
<i>in</i>	Assoc. Eng.	<i>9/16</i>
	Assoc. Eng.	
	Env. Scen.	
<i>the</i>	Secretary	<i>ca</i>

Note: _____

We are being forced to close the Enos Johnson mine because of very low uranium sale prices at this time.

We feel there is probably as much good ore developed out in this mine as we have mined in the past 6 years, as well as the ore in the old stock pile on the surface. This should make a very good mine when the price comes back up.

We will clean out all of our equipment from underground, but will leave the good ore in the pillars along the haulage way, and all haulage way timbers for support for future mining.

We will then block the adits.

We will remove all temporary surface buildings, supplies, scrap and debris ect.

Clean out all surface water courses.

Clean out the berm and water catch reservoirs.

Deepen the water bars, directing the water away from the mine area.

Re seed where applicable.

Blade up and block the mine road entrance and post "DANGEROUS KEEPOUT" signs.

This should make the mine area safe for a good long time. If this mine abandonment plan is not adequate advise us what is needed immediately.

Ray Williams
Ray Williams Mining